



DAM & DIKE INSTRUMENTATION & STRUCTURAL HEALTH MONITORING

References

- Abdel Moumen - Morocco , 2009
- Agcheh Dam - Iran , 2007
- Albian Sands - Canada
- Albigna Dam crack monitoring - Switzerland , 2010
- Alicura - Argentina , 2001
- Ambatovy - Madagascar , 2015
- Amoya - Columbia , 2009
- Ancoa Dam - Chile , 2010
- Ark1 - Turkey , 2011
- Arnaud Dam - Mauritius , 2015
- Artificial Water pool - Spain , 2013
- Water Reservoir Leak Detection - Spain , 2007
- Arbuckle Reservoir—USA , 2019
- Asadiyeh Dam - Iran , 2006
- Azad Dam - Iran , 2009
- Baba Haydar Dam - Iran , 2011
- Baft Dam - Iran , 2006
- Bagatelle - Mauritius , 2012
- Bagbasi Dam - Turkey , 2008
- Ban Chat - Vietnam , 2009
- Bar Dam - Iran , 2010
- BHP Minera Spence - Chile , 2018
- Bieu River - Vietnam , 2009
- Bimont - France , 2011
- Biolixivation Monitoring Tailing Dam - Chile , 2011
- Bitumen Joint Monitoring - Latvia , 2004
- Bobital - France , 2008
- Bordesca - Venezuela , 2009
- Butgenbach - Belgium
- Canal arnaud - Mauritius , 2013
- Canales Dam clay core - Spain , 2006
- Caren Dam - Chile , 2010
- Centrale de Carses - France , 2008
- Centrale de Dardennes - France , 2008
- Centrale Yate - Nouvelle Caledonie , 2009
- CFRD Afsar Dam Seepage Detection - Turkey 2014
- Chambon - France , 2009
- City of Greely - United States of America , 2003
- Cobbs Creek - USA , 2019
- Cotatay-Ondenon - France , 2009
- Dalesice Dam - Czech Rep , 2017
- Darunegar Dam - Iran , 2006
- Deriner Dam - Turkey , 2008
- Dlouhe Strane Dam - Czech Rep , 2018
- Eastmain 1A - Canada , 2007
- El Kebir - Tunisia , 2012
- El Mauro - Chile , 2010

DAM & DIKE INSTRUMENTATION & STRUCTURAL HEALTH MONITORING

References

- Emosson - Switzerland , 2000
- Ertan Dam - China , 1999
- Esch sur Sure - Luxembourg , 2010
- Folsom Dam - USA , 2012
- Futaleufu - Argentina , 2010
- Gamgoum - Tunisia , 2012
- Garan Dam - Iran , 2007 - 2009
- Gareh Aghach Dam - Iran , 2005
- Garvey Reservoir - California - USA , 2011
- Gavosham Dam - Iran , 2005
- Gelevard Dam - Iran , 2011
- Germychay Dam - Iran , 2009
- Ghalechay Dam - Iran , 2008
- Ghizghalesi Dam - Iran , 2010
- Gokcebel Dam - Turkey , 2008
- Gotvand Dam - Iran , 2011
- Grand Coulle Dam - WA - USA , 2002
- Grosbois - France , 2013
- Grouffre d'enfer - France , 2009
- Guri - Venezuela , 2010
- Jarreh Dam - Iran , 2004
- Jingping - China , 2006
- Joghan Dam - Iran , 2009
- Kaboodwal Dam - Iran , 2010
- Kalan Dam - Iran , 2008
- Kalivac Dam - Albania , 2010
- Kavsak Dam - Turkey , 2012
- Khandar Dam - Iran , 2006
- Khoda-Afarin Dam - Iran , 2009
- Khorasan Dams - Iran , 2005
- Kin-E Var Dam - Iran , 2005
- Kissir - Algeria , 2012
- Kochary Dam - Iran , 2010
- Koudiat Acerdoune - Algérie , 2009
- GERD Dam Leak Detection - Ethiopia , 2016
- La Romaine - Canada , 2010
- La Romaine 4 / Complexe Mista - Canada , 2019
- La Sillonniere sur la Vouraie - France , 2008
- La Tuqye - Canada , 2011
- Lac d'Estaris - France , 2019
- Laguna Dam - Chile , 2009
- Laguna Seca - Chile , 2010
- Las Bambas Tailing Dam - Peru , 2014
- Las Tortolas Muro Noroeste - Chile , 2019
- Las Tortolas Muro Principal - Chile , 2018
- Leak Detection Earth Dam - Slovenia , 2012
- LG-1 Dam - Canada , 1977
- LG-2 Dam - Canada , 1978
- Lom Pangar's Dam - Cameroon , 2015
- Los Pelambres - Chile , 2005
- Lower Mattagami River - Canada , 2014
- Lowman Power Plant - USA , 2006
- Luzzzone dam raising - Switzerland , 1997
- Mamloo Dam - Iran , 2007
- Manduraicu Dam - Colombia , 2014
- Manic 5 - Canada , 1970
- Manic - Canada , 1994
- Mareesburg - South Africa , 2018
- Merrill Creek - USA , 2008
- Mervent - France , 2008
- Metropolitan Water District - USA , 2005
- Muddy Run Dam (PA) - USA , 2018
- Nam Chien - Vietnam , 2009
- Nam Na 2 - Vietnam , 2010
- Nam Ngum 2 Leak Detection - Laos , 2010
- Nam Theun - Laos , 2009
- Narmasheer Dam - Iran , 2005
- Nepes - France , 007
- New Assiut - Egypt , 2013
- Ngoi Phat - Vietnam , 2010
- OLMOS - Peru , 2007
- Ourkiss - Algeria , 2012
- Ovejeria Dam - Chile , 2012
- Panneciére - France , 2009
- Penstock movement - Switzerland , 2013
- Perez Caldera - Chile , 2017
- Peribonka - Canada , 2006
- Plats - France , 2007
- Quellaveco Relaves - Chile , 2019
- Rapid Blanc Dam - Canada , 1992
- Research leak detection - Korea , 2011
- Retarding basin - Japan , 2000
- Ridges Bassin Dam - USA , 2006
- Rio Rancheria - Columbia , 2008
- Saf Saf - Algérie , 2011
- Sagenzhi Dam - Iran , 2011
- Sainte-Marguerite 3 - Canada , 1999
- Sangoon Waste Dam - Iran , 2006
- Sarabi Dam - Iran , 2008
- Sarrat - Tunisia , 2012
- Seneca Reservoir - USA 2008
- Sep - France , 2008
- Shabshishe CFRD Dam - Iran , 2009
- Sierra Gorda Tailing dam - Chile , 2013
- Smoky Falls - Canada , 2013
- Songloulou Dam - Cameroon , 2014
- Srepok 3 - Vietnam , 2009
- SYMADREM Digue du Rhone, France , 2018
- Ta Trach - Vietnam , 2009
- Tabellout - Algeria , 2014
- Talvar Dam - Iran , 2008
- Taunsa Dam - Pakistan , 2006
- Three Gorges Dam - China , 1996
- Tin Dam - Tunisia , 2015
- Tocomá - Venezuela , 2013
- Toiwar Dam - Pakistan , 2014

DAM & DIKE INSTRUMENTATION & STRUCTURAL HEALTH MONITORING

References

- Toulustouc Dam - Canada , 2005
- Urra 1 Dam - Columbia , 2008
- Val De La Mare Jersey - UK , 2013
- Valsamiotis - Greece , 2009
- Van Chan - Vietnam , 2010
- Vanyar Dam - Iran , 2009
- Vhermoso Dam - Chile , 2017
- Wadi Dayqah - Sultana of Oman , 2007
- Willemspolder Dike - Netherlands , 2015
- Yedigoza Dam DSS - Turkey , 2010
- Yedigoza Dam DSS - Turkey , 2010
- Zagroos Dam - Iran , 2010
- Zanjan Dam - Iran , 2010
- Zirdan Dam - Iran , 2004

Case studies

- [Val De La Mare dam Jersey - UK , 2013](#)
- [Arkun Dam, Artvin - Turkey , 2014](#)
- [Nam Ngum 2, Leak Detection - Laos , 2010](#)
- [Water Reservoir Leak Detection - Spain , 2009](#)
- [Koudiat Acerdoune Dam - Algeria , 2009](#)
- [Canales Dam Clay Core - Spain , 2006](#)
- [Bitumen Joint Monitoring - Latvia , 2004](#)
- [Deriner Dam, Artvin - Turkey , 2014](#)
- [Emosson - Switzerland , 2000](#)
- [Luzzone Dam Raising - Switzerland , 1997](#)

Selected Publications

- [Monitoring Dams and Levees with distributed Fiber Optic Sensing, Daniele Inaudi, Ivan Cottone, Angelo Figini, SHMII-6 2013](#)
- [Application of distributed Fiber Optic Sensory for SHM, D. Inaudi, B. Glisic, 2nd International Conference on Structural Health Monitoring of Intelligent Infrastructure -SHMII-2'2005, Shenzhen, China, November 2005](#)
- [SOFO®: Structural monitoring with fiber optic sensors, D. Inaudi, S. Vurpillot, G. Martinola, G. Steinmann , Fib Commission Meeting, Institute of structural engineering, University of applied sciences, Vienna, Austria - -Vol 40, 9 - 1999](#)

Selected Publications

- [Fibre Optic Methods for Structural Health Monitoring, Branko Glisic and Daniele Inaudi, John Wiley & Sons, Ltd - 2007](#)
- [Fabry-Perot Fiber Optic Sensors for Civil and Geotechnical Monitoring of Large Structures, Inaudi, Walder and Bulatao, International Workshop on Structural Health Monitoring, Stanford, September 2019](#)
- [Permanent Safety Assessment of Dams, Levees, Reservoirs, Waterways with Fiber Optic Distributed Sensing, Blin and Inaudi, ICOLD 2018 Conference, Vienna](#)
- [Fiber Optic Structural Health Monitoring for Dams, Cottone, Hydropower and Dams Conference, Porto 2019](#)

Available in Application Note

- Bridge Instrumentation and Structural Health Monitoring
- Building Instrumentation and Structural Health Monitoring
- Cryogenic Instrumentation & Safety Monitoring
- Dam & Dikes Instrumentation and Safety Monitoring
- FO Leak Detection System for Dams and Dikes
- FO Leak Detection in Process & Chemical Plants
- FO Leak Detection for Pipelines in Foundations
- FO Mining Instrumentation & Site Safety Monitoring
- FO LNG Pipeline Monitoring
- FO LNG Tank Monitoring
- Geothermal Monitoring
- Geotechnical & Structural Instrumentation
- Mining Instrumentation & Site Safety
- Nuclear Power Plants Instrumentation & Safety Monitoring
- Penstocks Instrumentation & Structural Health Monitoring
- Research Structural Health Assessment Systems
- Tunnel Instrumentation & Structural Health Monitoring
- Tailing Dams Monitoring